



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
Report Date: April 4, 2007

Supervisor 1024

**Mine Name:** East Veyo Cinder Knoll  
**Operator Name:** Sunroc Corporation  
**Dana Truman**  
**180 North 300 East**  
**St. George, Utah 84770**

**Permit number:** S/053/067  
**Date:** February 12, 2007  
**Time:** 3:00 pm

**Inspector(s):** Doug Jensen, Daron Haddock  
**Other Participants:** None  
**Mine Status:** Active

**Weather:** Cloudy

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

Inspected the site while I was in the area.

**Directions to Site:**

The site is located ~2 miles northeast of Veyo.

**Inspection Summary:**

The area has changed very little since the last inspection. No activity was occurring in the pit and it doesn't appear that any material has been excavated recently. No erosion or environmental concerns were noted.

**Conclusions and Recommendations:**

Continue to monitor the site when in the area.

**Inspector's Signature**

Daron Haddock

**Date:**

4/4/07

dh:pb

cc: Sunroc Corporation - Dana Truman

P:\GROUPS\MINERALS\WP\M053-Washington\S0530067-EastVeyoCinderKnoll\inspections\02122007insp.doc